



MATERIAL SAFETY DATA SHEET

SPARKO 42X-1635-0 VINYL TOPCOAT CLEAR

Section 1. € hemical Identification

SPARKO 42X-1635-0 VINYL TOPCOAT CLEAR Product Name

42X-1635-0 (X denotes gloss level) Product Code

Dangerous Goods Class

In Kilograms (Kg) Packaging Type

Use For wood coating

Section 2. Components

SURFACE COATINGS

Content **CAS Number**

Chemical Identity 35% Paint Resin

13% n-BAC 123 - 86 - 4

MEK URFA4% COATINGS 78 - 93 - 3

Toluene 5% 108 - 88 - 3

Iso-propyl Alcohol 11% 67 - 63 - 0

117 - 81 - 7Di-octyl Phtahalate 4%

Xylene 1330 - 20 - 728%

Section 3. Hazards Identification

Harmful if swallowed **Swallowing**

Skin Absorption May cause irritation to skin. May cause

sensitization by skin contact.

sInhalation COATINGS Trace component and residual monomer vapors COATINGS

may be irritating to the eyes, mucous

membrane, respiratory tract, and may produce symptoms of headache and/or nausea in poorly

ventilated areas.

SURFACE COATINGS

LUZON

REGIONAL OFFICE **TAGUIG**

1st Ave., Sta. maria Industrial Subd.,

Bagumbayan, Taguig City Tel #: (02) 506.8519; 837.0710 Fax #: (02) 519.1552

VISAYAS

HEADQUARTERS

CEBU 2F SEA Olympus Building, AC Cortes Ave., Mandaue City, 6014, Cebu Clty Tel #: (032) 421.7817; 421.7262; 421.7863 Fax#: (032) 346.1817; 421.7877

MINDANAO

REGIONAL OFFICE DAVAO

Unit A16 J. King Warehouse Complex Km. 3 Maa Road, Davao City 8000 Tel # (082) 244.1206 Fax #: (082) 285.2886

SURFACE COATI



Section 4. First-Aid Measures

Eye Contact: Direct contact may cause eye irritation.

Eye Contact : Thorough flushing with water for at least 15

minutes. Get immediate medical assistance.

Skin Contact ATINGS : Wash areas of contact repeatedly with soap and

water. Seek immediate medical assistance if

irritation persists.

Ingestion : NEVER INDUCE VOMITING. Seek immediate

medical assistance.

Inhalation : Prevent further exposure. Seek immediate

medical assistance if dizziness, nausea or

unconsciousness is experienced.

Section 5. Fire-Fighting Measures

SURFACE COATINGS

Fire Extinguishing : CO₂, foam, Dry powder. In case of larger fires,

water spray should be used.

In case of fire, formation of carbon monoxide, nitrogen oxide and traces of hydrogen cyanide is possible.

Special fire fighting

equipment : Self-contained breathing apparatus should be

used by Fire fighters. Do not let contaminated extinguishing water into the soil, groundwater or

surface waters.

Section 6. Accidental Release Measure

Small spills can be washed off with large amounts of water; spills of a larger scale must be <u>PROPERLY DISPOSED</u>. The product may be toxic to aquatic lives; DO NOT dispose in natural bodies of water. Proper protective equipment should be worn. Do not empty into drains.

Put on protective equipment. Remove sources of fire, ensure adequate ventilation/ exhaust ventilation. Keep unauthorized persons away.

SURFACE COATING

LUZON

REGIONAL OFFICE TAGUIG

1st Ave., Sta. maria Industrial Subd., Bagumbayan, Taguig City Tel #: (02) 506.8519; 837.0710 Fax #: (02) 519.1552 VISAYAS

HEADQUARTERS CEBU

ZEF SEA Olympus Building, AC Cortes Ave., Mandaue City, 6014, Cebu City Tel #: (032) 421.7817; 421.7262; 421.7863 Fax#: (032) 346.1817; 421.7877 MINDANAO

REGIONAL OFFICE DAVAO

Unit A16 J. King Warehouse Complex Km. 3 Maa Road, Davao City 8000 Tel # (082) 244.1206 Fax #: (082) 285.2886





Remove mechanically, cover remainders with wet, absorbent material (e.g. Sawdust, chemical binder based on calcium silicate hydrate, sand). After approx. one hour transfer to waste container. Keep damp in a safe ventilated area for several days.

Section 7. Handling and Storage

SURFACE COATI

Handling Ensure adequate ventilation or exhaust

> ventilation in the working area. Exhaust ventilation necessary if product is sprayed.

Avoid contact with skin and eyes.

Provide adequate ventilation and if necessary.

air extraction in working area. Explosion

protection required.

Storage keep container dry and tightly closed in cool and

well ventilated place.

Keep away from flame.

Section 8. Exposure Controls

Di-Octyl Phthalate

CAS No: 117-81-7

maximum limit of excess factor 1

N-Butvl Acetate

CAS No: 123-86-4

maximum limit of excess factor 4

Methyl Ethyl Ketone

CAS No: 78-93-3

maximum limit of excess factor 4

Iso-Propyl Alcohol

CAS No: 67-63-4TINGS

maximum limit of excess factor 4

 $5 \text{ mg/m}^3 \text{to } 10 \text{ mg/m}^3$ (8 hours average value)

150 ppm to 200 ppm

(8 hours average value)

200 ppm to 250 ppm (8 hours average value)

400 ppm to 500 ppm

(8 hours average value)

100 ppm to 125 ppm

Toluene CAS No: 108-88-3 (8 hours average value)

maximum limit of excess factor 1

SURFACE COATINGS

LUZON

REGIONAL OFFICE

TAGUIG

1st Ave., Sta. maria Industrial Subd., Bagumbayan, Taguig City Tel #: (02) 506.8519; 837.0710 Fax #: (02) 519.1552

VISAYAS

HEADQUARTERS

CEBU 2F SEA Olympus Building, AC Cortes Ave., Mandaue City, 6014, Cebu Clty

Tel #: (032) 421.7817; 421.7262; 421.7863 Fax#: (032) 346.1817; 421.7877

MINDANAO

REGIONAL OFFICE

DAVAO Unit A16 J. King Warehouse Complex Km. 3 Maa Road, Davao City 8000 Tel # (082) 244.1206

Fax #: (082) 285.2886



SURFACE COATINGS



Xylene

CAS No: 1330-20-7

maximum limit of excess factor 1

100 ppm to 125 ppm (8 hours average value)

SURFACE COATINGS

Personal Protection

Respiratory protection : Respiratory protection required in insufficiently

ventilated working areas and during spraying.

An air-fed mask, or for short periods of work, a combination of charcoal filter and particulate

filter is recommend.

Hand protection

SURFACE COATINGS

: Conditionally suitable materials for protective

gloves. Only suitable for brief exposure. In the event of contamination, change protective

gloves immediately.

Eyes protection : Wear eye/ face protection.

Body protection : Wear suitable protection clothing.

Protection and hygienic measures

Keep away from foodstuffs, drinks and tobacco. Wash hands before breaks and at end of the swork. Keep working clothes separate. Take off immediately all contaminated clothing.

Section 9. Physical and Chemical Properties

SURFACE COATINGS

Appearance : Clear to muddy

Color : slightly yellow to grayish white

Form : thick liquid

Odor : smell of solvent Boiling point : 118 (244.4

Flash point COATINGS: 28 (82.4)

Specific Gravity : 0.88 - 0.97

Explosive limits : 1% (lower)

10.8% (upper)

Solubility in Water: insoluble

SURFACE COATINGS

LUZON VIS.

REGIONAL OFFICE TAGUIG

1st Ave., Sta. maria Industrial Subd., Bagumbayan, Taguig City Tel #: (02) 506.8519; 837.0710 Fax #: (02) 519.1552 VISAYAS

HEADQUARTERS CEBU

2F SEA Olympus Building, AC Cortes Ave., Mandaue City, 6014, Cebu Clty Tel #: (032) 421.7817; 421.7262; 421.7863 Fax#: (032) 346.1817; 421.7877 MINDANAO

REGIONAL OFFICE

Unit A16 J. King Warehouse Complex Km. 3 Maa Road, Davao City 8000 Tel # (082) 244.1206 Fax #: (082) 285.2886

(close cup) RFACE COATINGS





SURFACE COATINGS

Section 10. Stability and Reactivity

Hazardous
Decomposition

Product : No hazardous decomposition when stored and

handled correctly

Hazardous Reaction : exothermic reaction with amines and alcohols;

reacts slowly with water forming CO2, in closed containers risk of bursting owing to increase of

pressure. E COATINGS

Section 11. Toxicological information

Acute toxicity ATINGS

LD₅₀ oral, rat

Eyes

more than 5000 mg/ kg Skin and mucous

membrane compatibility,

rabbit : skin 4 hours exposure – very slight irritant.

: very slight irritant

Section 12. Ecological information

Acute fish toxicity

LC₅₀ : 4500 ppm/4H

 LD_{50} : 17100 mg/Kg

Section 13. Disposal Consideration

SURFACE COATINGS

SURFACE COATINGS

SURFACE COATINGS

Do not allow to escape into waters, wastewater or soil.

The waste can be disposed of in a suitable incinerator under compliance with the relevant legislation.

SURFACE COATINGS

LUZON VIS

REGIONAL OFFICE TAGUIG

181 Ave., Sta. maria Industrial Subd., Bagumbayan, Taguig City Tel #: (02) 506.8519; 837.0710 Fax #: (02) 519.1552 VISAYAS

HEADQUARTERS

CEBU2F SEA Olympus Building, AC Cortes Ave.,
Mandaue City, 6014, Cebu Clty
Tel #: (032) 421.7817; 421.7262; 421.7863
Fax#: (032) 346.1817; 421.7877

MINDANAO

REGIONAL OFFICE DAVAO

Unit A16 J. King Warehouse Complex Km. 3 Maa Road, Davao City 8000 Tel # (082) 244.1206 Fax #: (082) 285.2886





After final product withdrawal, all residues must be removed from containers (drip-free, powder-free or paste -free). Once the product residues adhering to the walls of the containers have been rendered harmless, the product and hazard labels must be invalidated. Containers must be recycled in compliance with national legislation and environmental regulations.

Incineration in compliance with local regulations.

SURFACE COATINGS

Section 14. Transport Information

IMDG : 3
IATA/ICAO COATINGS : 3
DOT 49 CFR : 3

SPARKO

SURFACE COATINGS

Section 15. Regulatory Information

SURFACE COATINGS

Vinyl coating for wood application.

Section 16. Others

SURFACE COATINGS

SPAR D

SURFACE COATINGS



The data and information contained in this Material Safety Data Sheet is provided to the best of our knowledge and ability on existing hazards, properties and handling of this product as recommended. It is recommended that the user tests the product according to its purpose. The user is responsible for the proper, safe and lawful use of this product. The information contained in this MSDS is subject to change without further notice. ©20

SURFACE COATINGS

SURFACE COATINGS



LUZON

REGIONAL OFFICE TAGUIG

1st Ave., Sta. maria Industrial Subd., Bagumbayan, Taguig City Tel #: (02) 506.8519: 837.0710 Fax #: (02) 519.1552

VISAYAS

HEADQUARTERS CEBU

2F SEA Olympus Building, AC Cortes Ave., Mandaue City, 6014, Cebu City Tel #: (032) 421.7817; 421.7262; 421.7863 Fax#: (032) 346.1817; 421.7877

MINDANAO

REGIONAL OFFICE DAVAO

Unit A16 J. King Warehouse Complex Km. 3 Maa Road, Davao City 8000 Tel # (082) 244.1206 Fax #: (082) 285.2886





PRODUCT SPECIFICATION SHEET

SPARKO 42X-1635-0 Vinyl Topcoat Clear

CHEMICAL IDENTIFICATION

Product Description : SPARKO 42X-1635-0 VINYL TOPCOAT CLEAR

Product Code 42X-1635-0 (X denotes gloss level)

Available from 0 – 90 Sheen

SURFACE COATINGS

PRODUCT FEATURES

A Vinyl clear topcoat for wood-based and indigenous material substrates requiring excellent adhesion and flexibility. Available from 0 to 90 Sheen. It is also recommended for use on MDF, Pine, Rosewood, Teak and other types of wood/timber with high oil/wax content. Great for use with SPARKO glazes.

SUITABLE WOOD-BASED SUBSTRATES

SURFACE COATINGS

Wood, oily and waxy substrates, MDF, bamboo, rattan and other indigenous substrates.

CHARACTERISTICS

Gloss Level : 0 – 90 Sheen

Colour Availability : Clear

Sag Resistance

TECHNICAL SPECIFICATIONS

. 32% + 1%

SURFACE

Solid Content (by weight) : $32\% \pm 1\%$ Density (@ 25° C) : 0.95 Kg/L

Mixing Ratio : 1:2 (Topcoat), 1:3 (Washcoat)

Thinning (604 Thinner) : 35-80% by volume

Theoretical Spreading Rate : $5.89 \text{ m}^2/\text{L}$

*Approximate Drying Time: (@ 28°C, 74% humidity)

Dust Free = 20 - 30 min; Print Free = 20 - 30 min; Stacking = 24 hr

SURFACE COATINGS

LUZON

REGIONAL OFFICE TAGUIG

1st Ave., Sta. maria Industrial Subd., Bagumbayan, Taguig City Tel #: (02) 506.8519; 837.0710 Fax #: (02) 519.1552 VISAYAS

HEADQUARTERS

CEBU2F SEA Olympus Building, AC Cortes Ave.,
Mandaue City, 6014, Cebu CIty
Tel #: (032) 421.7817; 421.7262; 421.7863
Fax#: (032) 346.1817; 421.7877

MINDANAO

REGIONAL OFFICE

Unit A16 J. King Warehouse Complex Km. 3 Maa Road, Davao City 8000 Tel # (082) 244.1206 Fax #: (082) 285.2886

SURFACE COATINGS





*The drying time varies depending on film thickness, thinning and the environment.

Shelf Life @ 30°C
Packaging Sizes

: 12 months

1 L, 4 L, 18 L, 200 L



HEALTH AND SAFETY



Proper personal protective equipment must be worn while using this product. This product should also be used in a well ventilated spray booth. Avoid breathing in or smelling this product at all times. Please refer to our Material Safety Data Sheets (MSDS) for more health and safety details.







The information contained in this product specification sheet has been provided based on our laboratory results. The type, quality and characteristics of substrates used, the environment of the end-user, individual systems or processes employed by the end-user and other conditions are elements which are beyond our control and we therefore recommend that the end-user test the product for the specific application, substrate required under the en-users environment and other working conditions. Sparko will not be held liable for damages to the improper use of our products. All information stated above are subject to change without prior notice. ©20

SURFACE COATINGS







LUZON

REGIONAL OFFICE TAGUIG

1st Ave., Sta. maria Industrial Subd., Bagumbayan, Taguig City Tel #: (02) 506.8519; 837.0710 Fax #: (02) 519.1552

VISAYAS

HEADQUARTERS CEBU

2F SEA Olympus Building, AC Cortes Ave., Mandaue City, 6014, Cebu Clty Tel #: (032) 421.7817: 421.7262; 421.7863 Fax#: (032) 346.1817: 421.7877

MINDANAO

REGIONAL OFFICE DAVAO

Unit A16 J. King Warehouse Complex Km. 3 Maa Road, Davao City 8000 Tel # (082) 244.1206 Fax #: (082) 285.2886